



FIG. 1  
Private LAN









FIG. 3

FIG. 4



[illegible]



[illegible]

FIG. 7 DIRECTOR BOARD 1901



001600 39652500




FIG 8

FIG 8A







FIG 8B



1. The first group of people who are going to be affected by the new law are the people who are going to be affected by the new law.





FIG 9




F1610

Receive Datapath

420

CPU BUS 317  
REC CPU BUS



Message Bus Send Operation

FIG. 11A






FIG. 11








FIG. 11A  
FIG. 11B



Message Bus Send Operation Continued

F1611B





# Message Bus Receive Operation

FIG. 12A





FIG 12

FIG 12A  
FIG 12B



Message Bus Receive Operation Continued



F1412B

# Message Bus Acknowledgement Operation

F-19.13





FIG 1AA

Xmit CPU flow



F1414B

Xmit Msg flow





FIG 15A

Rec msg flow



F1615B

Rec cpu flow

